

UNITED STATES PATENT AND TRADEMARK OFFICE

UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office Address: COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandria, Virginia 22313-1450 www.usplo.gov

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.
10/524,763	04/26/2005	Matthias Muller	NY-DNAG-300-US	3415
²⁴⁹⁷² FULBRIGHT	7590 12/03/2007 & JAWORSKI, LLP		EXAMINER	
666 FIFTH AV	/E		ADDISU, SARA	
NEW TORK,	NY 10103-3198		ART UNIT	PAPER NUMBER
			3722	
			MAIL DATE	DELIVERY MODE
		•	12/03/2007	PAPER

Please find below and/or attached an Office communication concerning this application or proceeding.

The time period for reply, if any, is set in the attached communication.

Application/Control Number: 10/524,763

Art Unit: 3722

DETAILED ACTION

EXAMINER'S AMENDMENT

An examiner's amendment to the record appears below. Should the changes and/or additions be unacceptable to applicant, an amendment may be filed as provided by 37 CFR 1.312. To ensure consideration of such an amendment, it MUST be submitted no later than the payment of the issue fee.

Authorization for this examiner's amendment was given in a telephone interview with Mr. Crawford on 2/8/07.

The application has been amended as follows:

- Claim 11, line 3, after the word "trough" add the words "extending from said upper side"
- Claim 11, line 5, after the word "trough" and before the word "arrananged" add "extending from said upper side and".
- Claim 68, line 6, after the word "trough" add "in said upper side and".

Allowable Subject Matter

Claims 11-71 are allowed.

Regarding independent claims 11 and 68, the closest prior art to the instant invention is Ukegawa et al. (USP 6,017,172). UKEGAWA ET AL. teaches a cutting plate comprising an upper side, cutting edge, a first clamping trough (2: located on the top side of the insert) for clamping in a cutting tool arranged coaxially with respect to a

Application/Control Number: 10/524,763

Art Unit: 3722

second clamping trough (2: located on the bottom side of the insert) ('172, figure 1A, 1B). However, UKEGAWA ET AL. fails to anticipate or make obvious both troughs extending from the upper side of the insert.

Conclusion

Any inquiry concerning this communication or earlier communications from the examiner should be directed to Sara Addisu at (571) 272-6082. The examiner can normally be reached on 8:30 am - 5 PM.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Monica Carter can be reached on (571) 272-4475. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free).

Sara Addisu (571) 272-6082

> 5A 11/29/07

MONICA CARTER
SUPERVISORY PATENT EXAMINER

· Page 3